



Case Study

Superstar

Pisces and

Aquarius

Overview

Refurbishments were carried out on both Star Cruises' Superstar Pisces and Aquarius ships.



Project highlights

Name:	Star Cruises
Location:	Dry dock
Project Type:	Stage refurbishment
Building Type:	Cruise Ship vessel
Product Types:	Harlequin Cascade



HARLEQUIN
www.harlequinfloors.com

Case Study

Superstar Pisces and Aquarius

The requirement:

Stage refurbishment and new stage surface.



The solution

Harlequin removed the existing stages and replaced the plywood on both using two layers of Dricon® fire retardant treated 18mm timber onto Isorubber, fixed with tech screws through the plywood and Isorubber impact sound isolator.

The plywood joins were filled and sanded to a suitable finish before installing Harlequin vinyl top surfaces. Harlequin Cascade was then installed lengthways across both stages with seams welded and silicone sealant to the perimeter abutting walls.

The wooden plinths at the front of both stages were stripped of varnish, sanded and repaired then recoated with three coats of marine approved varnish.

Harlequin Cascade



If you would like further information, advice and samples please contact us on +44(0) 1892 514 888 or enquiries@harlequinfloors.com



HARLEQUIN
www.harlequinfloors.com